


ABSOLUTE INFRARED INSPECTION SERVICES 5043 West Lake Road Erie, PA 16505 814-835-9295	Thermal Diagnostics Report By: Craig Casler Level II Thermographer Level II ASNT
------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------

Customer:	XXXXXXXXXXXXXX
Date:	July 25, 2006
Location:	Exterior
Equipment:	Pad Mounted Transformer
Component:	H3 A
Voltage:	N/A
Amp / Load	N/A
I.D. #	

Thermal Image

Digital Image



Point 1 Temperature	N/A	Db Point 1	
Point 2 Temperature		Db Point 2	
Reference Temperature	N/A	Db Point 3	
Delta Temperature	N/A	Db Point 4	
Delta Temperature		Ambient Temperature	70

Comments: The corona discharge was verified with the corona camera. The perimeter of the H3 pistol grip at the top of the metal plate is the location of the arching. Black arching marks surround the perimeter of the pistol grip on the metal plate.

Repair Log

Repair Date	Description	Signature