



Comments: **A Great Find for Early Detection of Potential Problems.** The Top left thermal image has heat associated with discharge detected with the ultrasound Also notice the tracking marks above and below the warm area showing signs of tracking which are shown in the middle close up photos as well. The bottom image and photo revealed no heat but discharge was detected here as well with tracking marks also.